

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — February 2015

390. Mack tea cup radial arm cracking

We have received a report, from a UK registered inspection body, of failures on the radial arm to rotating centre attachment bores on several Mack tea cup rides. To facilitate the inspection of these areas the radial arms require removing from the rotating centre. It should be noted the manufacturer's operations manual does require bi-annual inspection of these areas. These rides are thought to be around 30 years old.



Committee Members: Mr. D Dadswell (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green, Mr. P Mitchell,
Mr. D Cox, Mr. M Thirkettle, Mr. W Gilbert, Mr. H Fisher, Mr. J Shilling & Mr. D Inman