



Number: B102R1011-0

Date: June 30, 1987

SERVICE BULLETIN

Effective Serial Numbers: 102-0208-86 through 102-0213-86

Ride: C.P. Huntington

Subject: Transmission Dipstick
Modification

The above noted C.P. HUNTINGTON trains are equipped with a non-vented dipstick for the transmission. CHANCE RIDES, INC. recommends that the following modification be made to these units to prevent transmission problems due to pressure build-up in the housing.

Perform the modification using the instructions below and the parts provided. All work must be performed by competent, qualified mechanics, capable of understanding the function of the parts and their proper installation. If there are any questions regarding the instructions or this modification, contact the CHANCE CUSTOMER SERVICE DEPARTMENT.

INSTALLATION INSTRUCTIONS

1. Remove the existing dipstick.
2. Disassemble the dipstick and the new dipstick handle components as illustrated.
3. Assemble the new components to the existing dipstick as shown. Discard the remaining parts.

