

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Sub-Committee

TECHNICAL BULLETIN - SEPTEMBER 1996

138. Emmett Miami Trip - Safety bars

We have been informed by NAFLIC members Howson Inspection Services Ltd. that they have become aware of fatigue fractures in car safety bar components of a K Emmett & Sons' Miami Trip type ride. These components are sometimes known as "Lamb Chops".

The areas in which the defects have occurred are not normally visible when the safety bars are assembled. Howsons are recommending that the components should be dismantled for visual and NDT inspection at each Thorough Examination.