

Number: S.B.QSR 001

Date: 8th Oct 1993

Supersedes: N/A

SERVICE BULLETIN

Effective Serial Numbers: All Quasars


Subject: Cracks found on 'H' Frame.

It has been noted that one Quasar has developed cracks on the 'H' frame upper pivot points, radiating from the hinge pin holes (see attached sketch).

All operators must inspect for cracks in this area. If any cracks are found, please inform the manufacturer and ensure that the ride is not used until repairs have been carried out.


A Repair bulletin will follow shortly.

QUASAR SUB-FRAME



CRACKS FOUND ON 'H' FRAME AT THIS POINT
BOTH SIDES

THIS FRAME



CRACKS RADIATING FROM HINGE PIN HOLES BOTH SIDES
AND RUNNING ACROSS BOX SECTION