



CHANCE RIDES, INC.
4219 Irving
Wichita, KS 67277-2328
U.S.A.
Phone: 1-800-242-6231 • FAX: 1-316-942-7416
Website: www.rides.com
E-mail: rides@rides.com

Bulletin No:	B408R1217-0
Release Date:	July 7, 1999
Effective Date:	July 7, 1999
Supersedes:	N/A
Completion Date:	August 7, 1999
Page:	1 of 2

SERVICE BULLETIN

Ride Manufacturer: CHANCE RIDES, INC. Affected Production Dates: 1/31/96 through 6/1/99

Ride Name: CHAOS Affected Serial Nos.: 408-00196 through 408-04499

Model No.: 408

Abstract of Issue:
Boom Inspection

Reason For Release:

Chance Rides, Inc. has become aware that cracks can form in and around the tilt head mounts on the boom of the above noted CHAOS amusement rides.

Action to be Taken:

Chance Rides, Inc. requires all owner/operators of these rides to inspect the boom in the area of the tilt head mount. This is an annual inspection.

Detail of Issue:

Perform the inspection described on the next page of this bulletin. If any indications are found, contact the CHANCE Customer Service Department immediately for instructions on further action to be taken. DO NOT ATTEMPT TO WELD OR OTHERWISE REPAIR THE BOOM, EXCEPT AS SPECIFICALLY INSTRUCTED BY CHANCE RIDES, INC.

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

NOTICE

Use only those components authorized, specified or provided by Chance Rides, Inc.

Chance Rides, Inc. SPECIFICALLY DISCLAIMS ANY LIABILITY for losses associated with any unauthorized alterations and/or modifications or additions and installations of unauthorized components.



CHANCE RIDES, INC.
4219 Irving
Wichita, KS 67277-2328
U.S.A.
Phone: 1-800-242-6231 • FAX: 1-316-942-7416
Website: www.rides.com
E-mail: rides@rides.com

Bulletin No:	B408R1217-0
Release Date:	July 7, 1999
Effective Date:	July 7, 1999
Supersedes:	N/A
Completion Date:	August 7, 1999
Page:	2 of 2

Ride Manufacturer: CHANCE RIDES, INC.

Affected Production Dates: 1/31/96 through 6/1/99

Ride Name: CHAOS

Affected Serial Nos.: 408-00196 through 408-04499

Model No.: 408

Detail of Issue (continued):

ANNUAL INSPECTION PROCEDURE

1. Visually inspect both sides of the boom in the areas shown.
2. If any cracks are found, contact the CHANCE Customer Service Department.

