



CHANCE RIDES, INC.
4219 Irving
Wichita, KS 67277-2328
U.S.A.
Phone: 1-800-242-6231 • FAX: 1-316-942-7416
Website: www.rides.com
E-mail: rides@rides.com

Bulletin No: B102R1227-0
Release Date: September 30, 1999
Effective Date: September 30, 1999
Supersedes: N/A
Completion Date: December 30, 1999
Page: 1 of 1

SERVICE BULLETIN

Ride Manufacturer: CHANCE RIDES, INC. Affected Production Dates: All
CHANCE MFG. CO., INC. Affected Production Dates: All

Ride Name: C. P. HUNTINGTON Affected Serial Nos.: All units

Model No.: 102


Abstract of Issue:
Coach Drawbar Inspection and Replacement

Reason For Release:

Coaches on early production C. P. HUNTINGTON trains were equipped with 30" drawbars. In 1982, the length of the drawbars was extended to 31-1/2". This additional length was added to facilitate easier access for maintenance of the coaches in the drawbar area.

Action to be Taken:

Chance Rides, Inc. requires that all owner/operator's of the above noted C.P. Huntington trains inspect the drawbars on all coaches. All 30" drawbars must be replaced with the 31-1/2" drawbar.



Detail of Issue:

Order and install the 31-1/2" drawbars, part number 1026111-002. The new drawbars are an exact replacement of the existing drawbar, except for the length.

The drawbar will be offered at a reduced price if ordered within 90 days of the release date of this bulletin.