

01-09 FBFR

Majestic Manufacturing, Inc.

Majestic Manufacturing, Inc. * PO Box 128
4536 State Route 7, New Waterford, Ohio 44445

Subject: Musik Express Aluminum Track

ATTN: OWNER/OPERATOR

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin must remain with the owner's manual at all times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m.-4:30p.m. E.S.T. ** Fax 330/457-7490.

SERVICE BULLETIN

Date: August 30, 2001



S.B. Number: 2001-02

Notice:

This bulletin pertains to the safe operation of your Musik Express. It has come to our attention that cracks have developed on the aluminum track where one track is bolted to the other.

The owner/operator must inspect the area around the singe bar (see diagram). If cracks are visible, they **MUST** be re-welded.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447 or toll free at 1-888-MAJ-RIDE.



Dedicated to Safety in the Amusement Industry