

TELEFAX

AmTech / Amusement Technologies Intl. Inc.

3306 N. Main St. Cleburne, TX 76033

Tel: 817-641-5045 * Fax: 817-645-9109

Web Site: www.Amtechintl.com

E-mail: E-mail@amtechintl.com

Date: January 3, 2003

ID #: SOO010303Z

Pages:

To: All Spin Out Owners

Safety Alert

Re: Sweep failure incident in Puerto Rico.

Tivoli Mfg. Ltd. has been informed of a structural failure, which caused the vehicle support sweep(1 of 6) to detach from the ride. This ride was being operated by Amusements of America in Puerto Rico. From information received through operators no life threatening injuries had occurred.

It is **absolutely necessary** that all vehicle support sweeps on all Spin Outs be inspected immediately according to the bulletin **SOSA005 issued July 1, 2001**. If any cracking is detected stop operation of ride immediately until proper repairs are made.

Please notify Tivoli, Ltd. or AmTech/ Amusement Technologies Intl. Inc. the results of the inspection.

For Tivoli Mfg. Ltd.
AmTech/ Amusement Technologies Inc.