



NUMBER : B408R1184-0

DATE : Sept. 12, 1997

SUPERSEDES :

SERVICE BULLETIN

Effective Serial Number: All Units

Ride: CHAOS

Subject: Inspection of Cylinder
Support Frames

Chance Rides, Inc. has become aware that it is possible for cracks to develop in the structural frame members which supports the main hydraulic lift cylinder on the CHAOS amusement rides noted above.

Chance Rides, Inc. requires all owner/operators to perform an annual visual inspection of all support frame members as outlined on the back of this bulletin. If any indications are found, contact Chance Customer Service for a repair procedure.

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

NOTICE

Use only those components authorized, specified or provided by Chance Rides, Inc.

Chance Rides, Inc. SPECIFICALLY DISCLAIMS ANY LIABILITY for losses associated with any unauthorized alterations and/or modifications or additions and installations of unauthorized components.

INSPECT ALL WELDS IN THE AREAS INDICATED BY ARROWS

